



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

April 5, 1988

To: File

From: Holland Shepherd, Reclamation Soils Specialist HWS

Re: Site Inspection, Deremo, M/037/025, San Juan County, Utah

On March 15, 1988, Frank Filas and I visited the Deremo Mine site east of Monticello, Utah. The mine has not been active this year, according to the annual report. No surface activity was apparent at the site.

We looked at the 1.1 acre mine pond, which had been graded and seeded in 1984. The pond is located on the Utah side of the mine, and separated from the Colorado side by a barbed wire fence. The revegetation effort appears to be effective, meeting the within 70% requirement of Rule M-10(12). It is recommended that this portion of the mine be released from any future reclamation obligation by the operator.

cc: L. Braxton  
F. Filas  
0817Q-12